SECRET

PRICRITY

OUT 65747 P 202041Z AUG 68 FM NPIC WASHDC TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB RUCLFGA/100TH SRW OL 19 MCCOY AFB FLA 20 Aug 88 2! 09 z RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD RUEAIIA/CIA WASH DC RUEOJFA/DIA ATTN: DIAXX-2 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUEFHQA/HQS USAF ΒT SECRET CITE NPIC 4395. SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI, DO; 100TH SRW FOR DISTRIBUTION CO, DCOI; HQ USAF FOR AFRDR OFFI25X1 PI FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER. FILE SUBJECT: EVALUATION OF GLASS LAMP MISSION G-038 CABLE SEC. 1. QUALITY SUMMARY: THIS MISSION PROVIDES IMAGE QUALITY IP&B/RD COMPARABLE TO PREVIOUS MISSIONS USING UNIT B-18. THE IMAGE QUALITY SECUR. IS INCONSISTENT FROM FRAME TO FRAME WITH A GENERAL IMPROVEMENT ISSG//AD TOWARDS THE END OF THE MISSION. THE GROUND RESOLUTION AND INTERPRE PSG/OC RRD REPRO PAGE 2 RUEADJU 60 S E C R E T ATD TATION SUITABILITY ARE FAIR TO GOOD. CLOUD COVER AND HAZE OBSCURE IEG APPROXIMATELY 15 PERCENT OF THE ENTIRE MISSION. FROD 2. MISSION DATA: SCIEN A. THE STANDARD "B" CONFIGURATION CAMERA, UNIT NUMBER 18, WEST WAS USED IN MISSION G-038 FLOWN ON 15 AUGUST 1968. THIS WAS EAST AN OPERATIONAL MISSION USING THE U-2 AIRCRAFT. MODE V WAS USED THROUGHOUT THE MISSION. M&S FGM B. FILM TYPE 3400 WAS USED THROUGHOUT THE MISSION. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN. ALL MATERIAL DIA-XX4 WAS PROCESSED TO A Ø.6 GAMMA AT A SPEED OF 2.32 (LOG E). SPAD 3. ORIGINAL NEGATIVE: DIA-AP A. EXPOSURE: THE FIRST PART OF THE MISSION IS SLIGHTLY 25X1 UNDEREXPOSED; HOWEVER, AS SOLAR ELEVATION INCREASED, THE EXPOSURE CMX BECAME ADEQUATE. B. DENSITY AND CONTRAST: GENERALLY MEDIUM; HOWEVER, THE

C. IMAGED DEGRADATIONS:

(1) BOTH SIDES: ROLLER CHATTER ON THE EDGES, STATIC FOG ADVANCE CY

AND FLARE ASSOCIATED WITH THE DATA BLOCK AND VERTICAL INDICATOR WITH TEXT

DOT ARE PRESENT THROUGHOUT.

PAGE 3 RUEADJU 60 S E C R E T

D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: HEAT SPLICES ARE PRESENT BETWEEN FRAMES 495 AND 496 AND IN FRAME 1027. A MANUFACTURER'S SPLICE IS CONTAINED IN FRAME 1952.

FIRST PART OF THE MISSION IS VERY THIN DUE TO UNDEREXPOSURE.

(2) 9L SIDE: HEAT SPLICES ARE LOCATED BETWEEN FRAMES 142 AND 143, 1199 AND 1200, AND 1499-1500, AND IN FRAME 311. FRAME 1827 CONTAINS A MANUFACTURER'S SPLICE.

E. AUXILIARY DATA: THE IR POSITION LAMP IS VERY WEAK AND THE FRAME COUNTER SKIPPED FRAME ØØ2 CAUSING A BIAS OF ONE BETWEEN TITLING AND DATA BLOCK.

F. OTHER: MINOR, ERRATIC METERING IS PRESENT THROUGHOUT

THE MISSION.

GP-1

4. POSITIVES: THE PRINTING AND PROCESSING WERE GOOD. SECRET ---END OF MESSAGE---

GROUP 1
Excluded from automatic
downgrading and
declassification